ECS Configuration Change request				P:	age 1 of 🎸	Pages
CCR No. 98- CO	Rev	Request Ty	pe CCR			
Priority Routine	Urgent	Emergency X	Affected Release	Rel: 2	Change Class	II
Title (description) GSFC SCSI Switch Cable Management Plan						
Documents Affected	Source Nos (RID, NCR, Action Item, EDC CCR, etc.) or Tech Reference					
920-TDG-012 Rev: 00			444			
			NA			
RTM Change	Start New Bas	eline X				
Problem Requirements for fail over design caused the reconfiguration of the GDAAC and the production of a new type of cable management plan.						
Proposed Solution The attached SCSI Switch Cable Management Plan reflects the as built at launch configuration for GDAAC						
Need by COB: 1/23/98	s					
Impact Analysis:						_
Organizations Affected:	B00 ☐ Q0 [x]	Contracts E	CS Chief Eng Rel. A	FOS Rel. C		x. T
Science Off	Security [Subcontrct	Sys. Eng	Sys Verf x		_
Cost:	None	Small	Medium	Large		
Schedule:	None	(Not exceeding \$100,000) Other	(\$100,000 to \$500,000)	(Over \$500,000)		
Additional LOC	140110	oue.	Man-Month	S		
Materials					·	_
Originator Tim. Wells ex	xt. 4021	Timothy E. Wells Signature	Temothy	5 W	- AS /-22-	98
Office M&O	Office Manager	Tom Jaeger Signature	Com les of	leeg_	//92/ Date	19 _E
Disposition /	Approved 💆	Approved w/Comm	nent Forw	ard 🔲	Disapproved [
Comments:	CB Chairperson	Terry Fischer Signature	Wfi	sker	//23/ Dai	<u> 5</u> 8
CM01OC96						ECS
ORIGINAL						2